


1. Electrical Drawing and Components



SPARE PARTS LIST MODEL 6240

1. Electrical Drawing and Components

Item	Parts Number	QTY.	Description
M1	3.3.01.06.004	1	Motor – Beater 220/1100W/50HZ
M2	3.2.01.02.033	1	Compressor – Tecumseh CAJ2446
M3	3.2.03.03.004	1	Fan Motor - Main
M4	3.2.01.01.002	1	Compressor – Mix
M5	3.2.03.01.001	1	Fan Motor - Mix
M6	3.3.01.01.001	1	Agitator Motor
JR	3.1.01.02.012	1	Thermal Overload Relay
KM1	3.1.01.01.010	1	Contact of Motor
KM2	3.1.01.01.010	1	Contact of Compressor
T	3.1.01.04.002	1	Transformer
TH	3.1.02.13.020	2	Thermostat PT100
PC1	2.2.1.01.0007	1	Power Board
PC2	2.2.1.01.0004	1	Microprocessor Control Board
S1	3.2.04.06.005	1	Pressure Switch – Main Compressor
S3	3.1.03.03.003	1	Power Switch
S4	3.1.03.01.004	1	Switch - Draw
S5/S6	3.1.03.04.009	2	Indicator “Mix Low”
Fuse	3.1.02.08.002	1	Fuse